

S E R V I C E N O T E

SUPERSEDES: NONE

HP 83752A Synthesized Sweeper

Serial Numbers: 0000A00000 / 9999Z99999

Instructions on replacing defective on/off power switch**Duplicate Service Notes:**

83751A-06

83751B-05

83752B-05

Situation:

The "Power" on/off switches on some of the 8375X Series Synthesized Sweeper have failed to latch in the "ON" position. After evaluating the switch, it appears the switch may have a mechanical reliability problem. Currently, there is no new design for the replacement switch.

Solution/Action:

If the "Power" on/off switch will not latch in the "ON" position, replace the switch.

DATE: March 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☐ IMMEDIATELY ☒ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: LABOR 1.0 Hours	
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE ☐ ON-SITE ☒ HP LOCATION	SERVICE INVENTORY: ☐ RETURN ☒ SCRAP ☐ SEE TEXT	USED PARTS: ☐ RETURN ☒ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		HP RESPONSIBLE UNTIL: March 1999
AUTHOR: DM	ENTITY: 5320	ADDITIONAL INFORMATION:	