

## S E R V I C E N O T E

SUPERSEDES: None

**85685A RF Preselector**

Serial Numbers: 2648A00413 / 2648A00530

**30V Tune Mod Kit****To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

P/N	Description
85685-60107	Modification Kit

**Situation:**

Instruments which have DAC Assembly with P/N 85685-60006 or 85685-60094 may fail Diagnostic #1 as described by the 85685A RF Preselector Installation, Verification, and Service manual chapter 14 pp. 1-4 (P/N 85685-90097).

**Solution/Action:**

The problem can be eliminated by installing modification kit 85685-60107. The kit contains the necessary parts and instructions and should be installed only on those instruments with serial numbers between 2648A00413 and 2648A00530 which fail Diagnostic #1. Any service inventory should be modified as specified.

DATE: October1995

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: Labor 2.0 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: November 1998
AUTHOR: ATB	ENTITY: 5340	ADDITIONAL INFORMATION:	