

MODIFICATION RECOMMENDED –  
CORRECTS MANUFACTURING OR DESIGN DEFECTS

**86130A-05A**

# **S E R V I C E                      N O T E**

Supersedes:  
86130A-05

## 86130A BitAlyzer Error Performance Analyzer

**Serial Numbers:** US41450819 and earlier.  
**Exception:** US41450824

**Assembly replacement solution provided by 86130A-05 to fix Intermittent PG output shutdown was not required. Refer to service note 86130A-06A.**

**To Be Performed By:** Agilent-Qualified Personnel

**Parts Required:**

P/N	Description	Qty.
NONE.		

**Situation:**

REFER TO SUPERSEDING SERVICE NOTE 86130A-06A.

**Solution/Action:**

REFER TO SUPERSEDING SERVICE NOTE 86130A-06A.

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR: 0.0 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE      AGILENT RESPONSIBLE UNTIL:		
AUTHOR: RBS      PRODUCT LINE: 8F			
ADDITIONAL INFORMATION: This service note has been superseded by 86130A-06A.			

© AGILENT TECHNOLOGIES, INC. 2003  
PRINTED IN U.S.A.



March 25, 2003