

MODIFICATION RECOMMENDED

DSA93004L-01

S E R V I C E N O T E

Supersedes:
None

DSA93004L - 30 GHz Digital Signal Analyzer

Serial Numbers: All

Acquisition board replacement for Agilent service center personnel

Parts Required:

P/N	Description	Qty.
None		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☐ ON SPECIFIED FAILURE ☒ AGREEABLE TIME	STANDARDS LABOR: 0.0 Hours	
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE ☐ ON-SITE ☒ SERVICE CENTER ☐ CHANNEL PARTNER	SERVICE INVENTORY: ☐ RETURN ☐ SCRAP ☐ SEE TEXT	USED PARTS: ☐ RETURN ☐ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE NO CHARGE AVAILABLE UNTIL: End of product support life		
AUTHOR: KO	PRODUCT LINE: 1A		
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2011
PRINTED IN U.S.A.

July 15, 2011

Rev. 18



Situation:

Acquisition board bandwidth must cover the bandwidth of the oscilloscope.

Solution/Action:

Refer to service note DSA93004L-02 for the correct selection and setting of the acquisition board bandwidth.