

DSO80604B-01B

S E R V I C E N O T E

Supersedes:
DSO80604B-01A

DSO80604B-80000 Series Oscilloscopes

Serial Numbers: MY46000101 - MY46000910
SG46000501 - SG46000802

Serial number break: MY46001001, SG46001001 and above do not need recommended modification.

During the normal warranty period instruments CDROM drive fails to identify itself, on 80000 series.
This is not a safety concern.

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:	Description	Qty.
54857-62601	Sub Assembly Power Supply	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY X ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR: 1.0 Hours
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE X SERVICE CENTER	SERVICE INVENTORY: X RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS: X RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT NO CHARGE AVAILABLE UNTIL: end of factory warranty
AUTHOR: MR PRODUCT LINE: PL1A		
ADDITIONAL INFORMATION:		

© AGILENT TECHNOLOGIES, INC. 2007
PRINTED IN U.S.A.



Situation:

Instrument fails to identify CDROM drive.

Solution/Action:

- 1. Remove old power supply sub assembly.**
- 2. Replace new power supply sub assembly.**