

S E R V I C E N O T E

SUPERSEDES: NONE

E1740A Time Interval Analyzer

Serial Numbers: 3323A00101 to 3323A00451, 3332A00417, 3458A00590
3548A00112 onwards

E1740A in 9490 system

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

Description	P/N	Qty
Exchange Assembly	E1740A-69021	1

Situation:

E1740As times out during diagnostic testing from a 9490 system but passes all the service center's calibration tests.

Solution / Action:

If the service center receives an E1740A that times out during diagnostic testing from a 9490 system but passes all the service center's calibration tests, then replace high speed board, E1740-68021/ E1740-68001.

Refer to service note E1740A-01 for disassembling and re-assembling instructions.

Order exchange assembly E1740A-69021 for replacement.

Reassemble E1740A and run calibration test again.

DATE: September 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR 0.5 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: September 1999
AUTHOR: FL	ENTITY: 0200		ADDITIONAL INFORMATION: