

S E R V I C E N O T E

SUPERSEDES: NONE

E2500A Frequency Agile Signal Simulator (8791 Model 10)**Serial Numbers:** 0000A00000 / 9999A99999**Replacement of Interconnect Cable between the 86792A Agile Upconverter and the 86790B Modulation Data Source.****Duplicate Service Notes:** E2500A-10, E2500B-06**Situation:**

At some time during the servicing of the 86792A Agile Upconverter (AUC). It may become necessary to remove the AUC from the system cabinet. This has proven to be difficult, as it was necessary to open the Modulation Data Source (MDS) rear-panel door to disconnect a data cable from the FM ADDER assembly before removing the AUC from the system cabinet.

Solution/Action:

When the AUC requires removal from servicing. It is recommended that the cable assembly that goes between the MDS and AUC is replaced with the following cables, part number's 86793-60028 and 86793-60029. The two cable assemblies will provide a convenient break point between the AUC and MDS during future servicing.

The cable assemblies should be connected as follows:

1. Part number 86793-60029 to the 86792A Agile Upconverter
2. Part number 86793-60028 to the 86790A Modulation Data Source.

DATE: 21 October 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

ENTITY:

ADDITIONAL INFORMATION:

DS

0400