# S E R V I C E N O T E

SUPERSEDES: NONE

# E2929A PCI-X Master Target Test Card, 133MHz

**Serial Numbers:**DE40300101 / DE40300192

### **USB** port draws excessive current from the Host System

To Be Performed By: Agilent-Qualified Personnel

Parts Required: None

#### **Situation:**

If the User connects the E2929A USB port to the host, up to 3 Amperes are drawn from the hosts 5V. This may lead to a defective USB port on the host system.

#### **Solution / Action:**

Remove the part E401 from the E2929A.

Visit the URL

'http://wwwbvs.germany.agilent.com/pl24/marketing/webcoe/intern/E2920A/Mode/Mode.html' for further information.

DATE: November 2000

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	<ul><li>■ IMMEDIATELY</li><li>□ ON SPECIFIED FAILURE</li><li>□ AGREEABLE TIME</li></ul>	STANDARDS:  LABOR 0.5 Hours
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE ☐ RETURN USED ☐ RETURN INVENTORY: ☐ SCRAP PARTS: ☐ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: Product Support Life
AUTHOR: RS	ENTITY: B100	ADDITIONAL INFORMATION:

© 2000 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

