A MODIFICATION ONLY - DOES NOT COMMUNICATE

E8400A-03

S E R V I C E N O T E

Supersedes: None

E8400A C-Size VXI mainframe

Serial Numbers: all

Replacement of E8400A impeller cooling fan

Parts Required:

| P/N | Description | Qty. |
|-------------|-----------------|------|
| 3160-0904 | Impeller Fan | 1 |
| E8401-47901 | Air Guide | 1 |
| E8400-01210 | Cover, Fan Base | 1 |

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: gls PRODUCT LINE: AR

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2003 PRINTED IN U.S.A.



June 10, 2003

Page 2 of 3 E8400A-03

Situation:

The original impeller fan E8400-68501 has been replaced by 3160-00904 which is not an exact replacement. To replace the fan requires replacement of the impeller fan, Air Guide, and "Cover, fan base".

Solution/Action:

Follow the instructions in the User/Service manual P/N E8400-90001 page 46 titled "Replacing the Impeller". In addition to the the Impeller fan, the Air Guide and the "Cover,fan base" must be replaced when the original impeller is replaced. The original impeller E8400-68501 was made by Comair Rotron Inc. The replacement Impeller 3160-0904 is made by EBN Industries.

.



Page 3 of 3 E8400A-03



