

Modification Recommended Service Note

Supersedes:
NONE

F8800B PROPSIM F64 Platform

Serial Numbers: FI64223241, FI64215041, FI64223392, FI64223361, FI64222281, FI64223393

The Problem – A batch of attenuators shipped from August 2023 could cause potential system issues.

Parts Required:

P/N	Description	Qty.
1827-2236	C Microwave Attenuator	16

ADMINISTRATIVE INFORMATION

ACTION	<input type="checkbox"/> ON SPECIFIED FAILURE	STANDARDS	
CATEGORY:	<input checked="" type="checkbox"/> AGREEABLE TIME	LABOR:	1.0 Hours
LOCATION	<input type="checkbox"/> CUSTOMER INSTALLABLE (No Parts involved)	SERVICE:	<input checked="" type="checkbox"/> RETURN
	<input checked="" type="checkbox"/> SERVICE CENTER	INVENTORY:	<input type="checkbox"/> SCRAP
CATEGORY:	<input type="checkbox"/> ON-SITE (active On-site contract required)		<input type="checkbox"/> SEE TEXT
	<input type="checkbox"/> CHANNEL PARTNERS	USED	<input checked="" type="checkbox"/> RETURN
		PARTS:	<input type="checkbox"/> SCRAP
			<input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	Nov 1 st 2027
	<input checked="" type="checkbox"/> Calibration Required	PRODUCT LINE:	13
	<input type="checkbox"/> Calibration NOT Required	AUTHOR:	AA

ADDITIONAL INFORMATION:

Situation:

Due to a possible issue on a batch of IC attenuators found in the F8800B Channel Emulators shipped since August 2023. Keysight have agreed to implement a service note to replace the at risk F8800B channel emulators IC attenuators that could exhibit this issue.

Solution/Action:

The risk of failure is low but on the next service event Keysight will proceed to check the serial number of the unit and if it is at risk will proceed to replace the attenuators within the unit under this service note.

Revision History:

Date	Service Note Revision	Author	Reason for Change
14 November 2025	01	Andrew Alford	As Published