# MODIFICATION RECOMMENDED - CORRECTS MANUFACTURING OR DESIGN DEFECTS

J1981B-02

# SERVICE NOTE

Supersedes: NONE

## J1981B VQT

Serial Numbers: [0000A00000 / 9999Z99999]

### A number of J1981B VQT testers have defective power supplies

To Be Performed By: Agilent-Qualified Personnel

**Parts Required:** 

P/N Description Qty.

**J3953-89001** Power supply 1

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION	[[]] IMMEDIATELY	STANDARDS:	
CATEGORY:	[[]] ON SPECIFIED FAILURE	LABOR: 2.0 Hours	
	X AGREEABLE TIME		
LOCATION	[[]] CUSTOMER INSTALLABLE	SERVICE [[]] RETURN	USED X RETURN
CATEGORY:	[[]] ON-SITE	INVENTORY: [[]] SCRAP	PARTS: [[]] SCRAP
	X SERVICE CENTER	X SEE TEXT	[[]] SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: September 2004	
		<u> </u>	
AUTHOR: DM	PRODUCT LINE: 2J		
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2002 PRINTED IN U.S.A.



Page 2 of 2 SN J1981B-02

#### **Situation:**

A number of J1981B VQT testers were received from the vendor with defective power supplies.

#### **Solution/Action:**

If unit serial number matches the list below it must be sent to a service center to have the power supply replaced. Please return defective power supplies to:

Agilent Technologies 5070 Centennial Blvd. Colorado Springs, CO 80919

Attn: Ron Mallette

SG41370236

SG42170264

SG42170265

SG42170266

SG42170267

SG42170268

SG42170269

SG42170270

SG42170271

SG42170272

SG42170273

SG42170274

SG42170275

SG42170276

SG42170277

SG42170279 SG42180103

SG42180106

SG42190101

SG42210101

SG41370238

SG41370240

SG41370241

SG41370243

SG41370245

SG41370246

SG41370249

SG41370250

SG41370251

SG41370253

SG41370254 SG41370255

SG41370256

SG42170257

SG42170258

SG42170259

SG42170260

SG42170261

SG42170262

SG42170263

SG42210102