

S E R V I C E N O T E

SUPERSEDES: None

J2302A Internet Advisor

Serial Numbers: 0000A00000 / 3432A00509

New replacement assemblies allow full speed operation when used with high speed parallel adapters

To Be Performed By: Agilent-Qualified Personnel

Assemblies:

- 5063-6239 DOS 16MegBytes Board Assembly
- 5063-6241 Exchange DOS 5063-6239
- 5063-6238 DOS 4MegBytes Board Assembly
- 5063-6240 Exchange DOS 5063-6238

Continued

DATE: October 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 1.5 Hours		
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: October 1996		
AUTHOR: NB	ENTITY: 0800	ADDITIONAL INFORMATION:			

Situation:

The Parallel Port design does not allow full speed operations when used with High Speed Parallel adapters.

	New Assembly	Old Assemblies
16MByte (New)	5063-6239	5063-5160, 5063-1873
16MByte(Exch)	5063-6241	5063-5134
4MByte (New)	5063-6238	J2300-62902, 5063-1872
4MByte (Exch)	5063-6240	5063-5133

Solution/Action:

The old DOS assembly resident within the instrument must be exchanged with one of the new assemblies listed above.