

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

J6800A-04B

S E R V I C E

N O T E

Supersedes:
J6800A-04A

J6800A Agilent Network Analyzer

Serial Numbers: ALL units prior to and including EC:03:03

J6800A instruments with EC codes prior to and including EC:03:03 MUST have hardware upgrades in order to work with software revision 1.2.30 and beyond.

Parts Required:

Parts	Description	Qty.
-------	-------------	------

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: DM PRODUCT LINE: 2J

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2003
PRINTED IN U.S.A.



Agilent Technologies

May 27, 2003

Situation:

All units prior to EC:04:04 must have hardware upgrades applied in order to work with newer versions of software.

Solution/Action:

Service centers receiving J6800A prior to EC:04:04 must trans-ship the units to one of two sites participating in the “enhancement program.” The two sites being used are as follows:

REGION

All regions:

REPAIR FACILITY

CSO SINGAPORE
Agilent Technologies Singapore Pte. Ltd
1 Yishun Avenue 7
Singapore 768923
Attn: Sreedhar Pagolu
+65 6-215-4112