L4490A-01A

<u>SERVICE NOTE</u>

Supersedes: L4491A-01

L4490A 2U RF/Microwave Switch Platform

Serial Numbers: MY00000000 - MY48000146

34945EXT modules purchased after June 1, 2008 require L4490A mainframe firmware revision 2.33 or greater.

Parts Required:

P/N Description Qty.

NONE

Situation:

34945EXT modules purchased after June 1, 2008 has new microprocessor that needs L4490A mainframe firmware version 2.33 or greater in order to work.

Solution/Action:

Update the mainframe firmware to version 2.33 or greater by following the procedure in Chapter 3 "Software Installation and Configuration" under "Firmware and Driver Updates" section of the L4490A/L4491A RF Switch Platform User's Guide manual.

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: TP	PRODUCT LINE: SP
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2008 PRINTED IN U.S.A.



Page 1 of 1

September 22, 2008

Rev. 14