

MODIFICATION RECOMMENDED

M9018A-07

S E R V I C E N O T E

Supersedes:
NONE

M9018A - 18 slot PXIe Chassis

Serial Numbers: TW00000000 through TW54340100

Unable to install PXI modules due to chassis insufficient height clearance

Parts Required:

P/N	Description	Qty.
M9018-69106	18-slot PXIe Refurbished Backplane Exchange Assembly(exclude fan and power supply assemblies)-exch	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: MODIFICATION RECOMMENDED		
ACTION X ON SPECIFIED FAILURE CATEGORY: <input type="checkbox"/> AGREEABLE TIME	STANDARDS LABOR: 0.5 Hours	
LOCATION <input type="checkbox"/> CUSTOMER INSTALLABLE CATEGORY: <input type="checkbox"/> ON-SITE (active On-site contract required) X SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE X RETURN INVENTORY: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED X RETURN PARTS: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 11/1/2015	
<input type="checkbox"/> Calibration Required X Calibration NOT Required	PRODUCT LINE: BL AUTHOR: TP	
ADDITIONAL INFORMATION:		

Situation:

It has been found that some chassis have insufficient height clearance, resulting in the inability to install PXI modules into the chassis. Typically this could occur in slots 1, 16, 17, and 18 of the chassis.

Solution/Action:

Replace with M9018-69106 or later version of backplane exchange assembly.

Revision History:

Service Note Revision	Date	Author	Reason For Change
01	9/30/14	TP	As published