

Modification Recommended Service Note

Supersedes:
NONE

M9046A PXIe Chassis: High-Power, 18-slot, 24 GB/s

Serial Numbers: TW00000000 - TW60500937

Manufacturing ID Number: 1C00000000 - 1C60500940

System is not able to enumerate M9135A module.

Parts Required:

P/N	Description	Qty.
M9046-69101	NFTS Refurbished core 18-slot PXIe Chassis, Exch.	1
M9046-66101	18-slot PXIe Chassis, new core Exch.	1

ADMINISTRATIVE INFORMATION

ACTION	<input checked="" type="checkbox"/> ON SPECIFIED FAILURE	STANDARDS	
CATEGORY:	<input type="checkbox"/> AGREEABLE TIME	LABOR:	0.5 Hours
LOCATION	<input type="checkbox"/> CUSTOMER INSTALLABLE (No Parts involved)	SERVICE:	<input checked="" type="checkbox"/> RETURN
	<input checked="" type="checkbox"/> SERVICE CENTER	INVENTORY:	<input type="checkbox"/> SCRAP
CATEGORY:	<input type="checkbox"/> ON-SITE (active On-site contract required)		<input type="checkbox"/> SEE TEXT
	<input type="checkbox"/> CHANNEL PARTNERS	USED	<input checked="" type="checkbox"/> RETURN
		PARTS:	<input type="checkbox"/> SCRAP
			<input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	November 01, 2025
	<input type="checkbox"/> Calibration Required	PRODUCT LINE:	BL
	<input checked="" type="checkbox"/> Calibration NOT Required	AUTHOR:	TP

ADDITIONAL INFORMATION:

Situation:

It has been found that when M9135A module is installed in the affected M9046A chassis, the modules may not enumerate.

Solution/Action:

Replace the chassis core by ordering the M9046A (M9046-69101 or M9046-66101). Refer to “Replacing Chassis Core Assembly” section in the [Keysight M9046A Service Guide](#) for instructions on how to replace the core assembly.

Revision History:

Date	Service Note Revision	Author	Reason for Change
10 Sep 2024	01	TP	As Published