

MODIFICATION RECOMMENDED

M9502A-05

S E R V I C E N O T E

Supersedes:
NONE

M9502A AXIe 2-Slot Chassis

Serial Numbers: TW00000000-TW54270100

M9505-00230 Embedded System Module (ESM) USB option may have USB connection problem

Parts Required:

P/N	Description	Qty.
M9505-00231	AXIe embedded system module with USB	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION X ON SPECIFIED FAILURE CATEGORY: <input type="checkbox"/> AGREEABLE TIME	STANDARDS LABOR: 0.5 Hours	
LOCATION X CUSTOMER INSTALLABLE CATEGORY: <input type="checkbox"/> ON-SITE (active On-site contract required) X SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE X RETURN INVENTORY: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED X RETURN PARTS: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 8/1/2017	
<input type="checkbox"/> Calibration Required X Calibration NOT Required	PRODUCT LINE: BL AUTHOR: TP	
ADDITIONAL INFORMATION: Only affected on the ESM USB M9505-00230.		

Situation:

M9505-00230 ESM USB option may have USB connectivity problem.

Solution/Action:

If you experience USB connectivity issue, replace the M9505-00230 ESM USB option with M9505-00231 ESM USB option.

Revision History:

Service Note Revision	Date	Author	Reason For Change
01	8/25/14	TP	As published