

# MODIFICATION RECOMMENDED

## M9505A-06

# S E R V I C E N O T E

Supersedes:  
NONE

## M9505A AXIe 5-Slot Chassis

Serial Numbers: TW00000000-TW54270100

**M9505-00230 Embedded System Module (ESM) USB option may have USB connection problem**

### Parts Required:

P/N	Description	Qty.
M9505-00231	AXIe embedded system module with USB	1

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
<b>MODIFICATION RECOMMENDED</b>		
ACTION X ON SPECIFIED FAILURE CATEGORY: <input type="checkbox"/> AGREEABLE TIME	STANDARDS LABOR: 0.5 Hours	
LOCATION X CUSTOMER INSTALLABLE CATEGORY: <input type="checkbox"/> ON-SITE ( <b>active On-site contract required</b> ) X SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE X RETURN INVENTORY: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED X RETURN PARTS: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 8/1/2017	
<input type="checkbox"/> Calibration Required X Calibration NOT Required	PRODUCT LINE: BL AUTHOR: TP	
ADDITIONAL INFORMATION: Only affected on the ESM USB M9505-00230.		

**Situation:**

M9505-00230 ESM USB option may have USB connectivity problem.

**Solution/Action:**

If you experience USB connectivity issue, replace the M9505-00230 ESM USB option with M9505-00231 ESM USB option.

**Revision History:**

Service Note Revision	Date	Author	Reason For Change
01	8/25/14	TP	As published