Modification Recommended Service Note

Supersedes: NONE

N5750A DC System Power Supply, 150V, 5A, 750W

Serial Numbers: Refer to Table 1

The Problem – Duplicated MAC addresses were identified in limited units.

Parts Required:

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

ACTION	[X] ON SPECIFIED FAILURE	STANDARDS			
CATEGORY:	[[]] AGREEABLE TIME	LABOR: 1 Hour			
LOCATION	[[]] CUSTOMER INSTALLABLE (No Parts involved)	SERVICE: []] RETURN USED []] RETURN			
	[X] SERVICE CENTER	INVENTORY: [[]] SCRAP PARTS: [[]] SCRAP			
CATEGORY:	[[]] ON-SITE (active On-site contract required)	[X] SEE TEXT [X] SEE TEXT			
	[[]] CHANNEL PARTNERS				
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: 14th Aug 2026			
	[[]] Calibration Required	PRODUCT LINE: SP			
[X] Calibration NOT Required		AUTHOR: LIM ZHAN MING			

ADDITIONAL INFORMATION:

Not applicable



Situation:

Serial number listed in Table 1 have been found to contain duplicated MAC addresses.

Table 1: Affected Serial Number

US23D6223A	US23D6227R	US25P75163	US25P75323
US23D6224R	US25P74803	US25P75203	US25P75383
US23D6225R	US25P75043	US25P75223	
US23D6226R	US25P75123	US25P75243	

Solution/Action:

Please contact the Keysight Technologies Customer Contact Center at www.keysight.com/find/contactus for MAC address reprogramming of the affected units.

Revision History:

Date	Service Note Revision	Author	Reason for Change	
13 th Aug 2025	01	LIM ZHAN MING	As Published	