Information Only Internal Only Document Service Note

Supersedes: NONE

| | | Б | 0 1 | 00011 | 0 - 4 | 750 | |
|----------|-----------|--------|-----------|--------|---------|--------|-----|
| N5751A | L)(:Svste | m Powe | r Sunnly | 300 \/ | 25A | /b() ' | W |
| 140/01/1 | | | i Guppiy, | 000 V | , 2.0 / | , , 00 | A A |

Serial Numbers: US23D6235R

The Problem – Duplicated MAC addresses were identified in limited units.

Parts Required:

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

[[]] Calibration Required PRODUCT LINE: SP
[X] Calibration NOT Required AUTHOR: LIM ZHAN MING

ADDITIONAL INFORMATION:



Situation:

Serial number listed has been found to contain duplicated MAC address.

Solution/Action:

Refer to the procedure for MAC address reprogramming:

Procedure to change MAC address in N57xx and N87xx.docx

**Please ensure that each MAC address is assigned to its corresponding serial number as listed in Table 2.

Table 2: Serial Number and its corresponding MAC Address

| Serial Number | MAC Address | | |
|---------------|--------------|--|--|
| US23D6235R | 8009021A1E60 | | |

Revision History:

| 1 | | |
|-----|--------------|--------------|
| 1 L | IM ZHAN MING | As Published |
| | | |
| | | |
| | | |
| | | |