N9030A-02

<u>SERVICE NOTE</u>

Supersedes: NONE

N9030A PXA Signal Analyzer

Serial Numbers: ALL

A16 Reference Assembly Requires Instrument Software Upgrade

The A16 Reference Assembly, p/n N9020-60188, requires SW revision A.10.52 or later.

Parts Required: NONE

ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION: | |
|------------------------------|------------------|
| INFORMATION ONLY | |
| AUTHOR: BS | PRODUCT LINE: 12 |
| ADDITIONAL INFORMATION: | |
| | |

© AGILENT TECHNOLOGIES, INC. 2012 PRINTED IN U.S.A.



December 17, 2012

Rev. 19

Page 2 of 2 N9030A-02

Situation:

The A16 Reference assembly, p/n N9020-60188, contains revised circuitry due to parts discontinuance, and the control of this new circuitry requires that the instrument software be updated on early instruments. Instrument specifications are unchanged.

Solution/Action:

The Instrument software must be revision A.10.52 or later for the Reference Assembly to function. The latest N9030A PXA software can be down loaded for www.agilent.com/find/xseries software