# N9912A-06

# <u>SERVICE NOTE</u>

Supersedes: NONE

# N9912A - FieldFox RF Analyzer

**Serial Numbers: ALL** 

## New I/O Parts Due to FieldFox System Board Change

**Parts Required:** 

P/N Description Qty.

N9923-60023 I/O Panel Assembly 1

## **ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: DYCS	PRODUCT LINE: WN
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2011 PRINTED IN U.S.A.



December 7, 2011

Page 1 of 2

Page 2 of 2 N9912A-06

#### **Situation:**

The FieldFox system board has been replaced with a new version with better reliability and ROHS compliance. The new system board is equipped with a micro-SD card reader, replacing the old mini-SD card reader.

### Old I/O input with mini-SD card reader



New I/O input with micro-SD card reader.



#### **Solution/Action:**

When ordering the new system board, you must also order I/O Panel Assembly N9923-60023. This assembly contains a new side connector panel and overlay.

The replacement procedure is found in the Service Guide, N9912-90003. Please refer to the Chapter 7 section titled, "Removing and Replacing the Case Group Parts."