

# Modification Recommended Service Note

Supersedes:  
NONE

## RP7972A Regenerative Power System

Serial Numbers: MY60000101 – MY60002000

The Problem – Incorrect label of “Float Voltage Rating”.

### Parts Required:

P/N	Description	Qty.
RP7972A-80001	Label Set for RP7972A	1

### ADMINISTRATIVE INFORMATION

ACTION	<input checked="" type="checkbox"/> ON SPECIFIED FAILURE	STANDARDS	
CATEGORY:	<input type="checkbox"/> AGREEABLE TIME	LABOR:	0.5 Hour
LOCATION	<input checked="" type="checkbox"/> SERVICE CENTER	SERVICE:	<input type="checkbox"/> RETURN
CATEGORY:	<input type="checkbox"/> ON-SITE (active On-site contract required)	INVENTORY:	<input type="checkbox"/> SCRAP
	<input type="checkbox"/> CHANNEL PARTNERS		<input checked="" type="checkbox"/> SEE TEXT
USED	<input type="checkbox"/> RETURN	PARTS:	<input checked="" type="checkbox"/> SCRAP
			<input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	30 <sup>th</sup> June 2024
	<input type="checkbox"/> Calibration Required	PRODUCT LINE:	SP
	<input checked="" type="checkbox"/> Calibration NOT Required	AUTHOR:	LIM ZHAN MING

ADDITIONAL INFORMATION:  
No impact on service inventory

### Situation

For the Serial Number listed the value of “Float Voltage Rating” has printed incorrectly on the label. The  $\pm 2000V$  label is incorrect and should be replaced with  $\pm 1000V$  label as shown in Figure 1.

However, there is no impact on the product performance.




Figure 1: Incorrect label

### Solution/Action:

When sending the instrument to the service centre for calibration or repair, label will be changed accordingly.

### Revision History:

Date	Service Note Revision	Author	Reason for Change
23 <sup>rd</sup> June 2023	01	LIM ZHAN MING	As Published