

U1282A-02

# Modification Recommended Service Note

Supersedes:  
NONE

## U1282A Handheld Digital Multimeter

Serial Numbers: MY00000000 / MY56999999

**The Problem** –Interference observed in the DC current measurement below 80MHz environment

### Parts Required:

P/N Description Qty.

NONE

### ADMINISTRATIVE INFORMATION

ACTION	<input type="checkbox"/> ON SPECIFIED FAILURE	STANDARDS	
CATEGORY:	X AGREEABLE TIME	LABOR:	0.5 Hours
LOCATION	<input type="checkbox"/> CUSTOMER INSTALLABLE	SERVICE:	<input type="checkbox"/> RETURN
CATEGORY:	<input type="checkbox"/> ON-SITE (active On-site contract required)	INVENTORY:	X SCRAP
	X SERVICE CENTER		USED PARTS: <input type="checkbox"/> SCRAP
	<input type="checkbox"/> CHANNEL PARTNERS		<input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	15-Dec-2017
	<input type="checkbox"/> Calibration Required	PRODUCT LINE:	GM
	X Calibration NOT Required	AUTHOR:	SW

ADDITIONAL INFORMATION:

**Situation:**

The U1280 series handheld digital multimeter is susceptible to interference in DC current measurement below 80MHz environment. The filter design of the product did not sufficiently attenuate external noise/RF signal in the current measurement path. Customers may observe some random fluctuating readings in a noisy RF environment.

**Solution/Action:**

Keysight Technologies has carried out a product enhancement on the DC current measurement below 80MHz environment.

Customers who have concern on the interference observed in the DC current measurement below 80MHz environment, may contact Keysight Technologies' Customer Contact Center at [www.keysight.com/find/contactus](http://www.keysight.com/find/contactus) for repair services.

**Revision History:**

Date	Service Note Revision	Author	Reason for Change
13 Dec 2016	01	SW	As Published