

U2001A-04B

S E R V I C E

N O T E

Supersedes:
U2001A-04A

U2001A - 10MHz – 6GHz USB Power Sensor

Serial Numbers: MY47100143 to MY47100239

USB sensor returns incorrect power reading when offset is introduced programmatically with the measurement unit is in Watt. The impacted firmware revision is A1.01.01.

Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: WPC	PRODUCT LINE: WC
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2010
PRINTED IN U.S.A.

November 30, 2010

Rev. 17



Situation:

When an offset value is introduced programmatically and the measurement unit is in Watt, the USB power sensor will return incorrect power measurement. The impacted firmware revision is A1.01.01.

Solution/Action:

Customer is recommended to update the USB sensor with the latest revision of firmware. The latest revision of firmware can be downloaded from Agilent web site.