

U8903A-06

S E R V I C E N O T E

Supersedes:
NONE

Agilent U8903A Audio Analyzer

Serial Numbers: All

Inaccurate Measurement Reading after Preset

The impacted firmware revision is 2.10.1.0 only

Parts Required:

P/N	Description	Qty.
NONE		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: LCW	PRODUCT LINE: WC
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2012
PRINTED IN U.S.A.

January 9, 2012

Rev. 19



Situation:

The U8903A is unable to provide an accurate reading after the user presses the “Preset” button to reset the U8903A to factory default setting.

Solution/Action:

There are two ways to resolve this issue:

- a) Re-boot the U8903A (after re-boot, the U8903A will back to factory default setting)
- b) Perform “Self-Test” for the “ADC & Range Test” according to the procedure below:

Press “System” → “Service” → “Self-Test” → “Customize Test” → “Deselect All” → Select “ADC & Range Test”

Once step (a) or step (b) is done, the U8903A will able to function as per the performance specified in the datasheet.