

S E R V I C E N O T E

SUPERSEDES: NONE

**Z2030-90200 DCT-3 Phone Adapter Rev 1.0 and Z2030-60014-05
System Connector PCB to Adapter PCB****Serial Numbers:** All Date Codes as Cables are Replaced**Tests have shown that spraying the connector increases the life and reliability of approximately 3 times on a sample of 3 cables of the system cable connector.****To Be Performed By:** Agilent-Qualified Personnel
Customer may perform this procedure if necessary**Parts Required:**

P/N	Description
64-4315	Radio Shack Tuner Control Cleaner & Lubricant
PN Z2030-90345	Tuner Control Cleaner & Lubricant

Situation:

Refer to the Action section of this Service Note for information on increasing the longevity and reliability of Adapter Cables.

Solution / Action:

On all new adapters, apply the cleaner & lubricant spray into the contact at both ends of the system connector cable prior to installation of the cable into the adapter. Be sure to spray each connector. Do not over spray, i.e., the connector should not be dripping. Field units should have cables sprayed as they are replaced.

DATE: September 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR 1.0 Hours	
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		
AUTHOR: MS		AGILENT RESPONSIBLE UNTIL: September 2001	
ENTITY: 3122		ADDITIONAL INFORMATION: Alt author JO/3759	