

S E R V I C E N O T E

SUPERSEDES: None

Z3825A GPS Timing Module**Serial Numbers:** 3723A00101 through 3723A00760**Notification of Product Extended Warranty****To Be Performed By:** Agilent Repair Center or Factory Only**Tools Required:**

Specified in standard repair instructions for this product, on file at repair location or factory.

Situation:

The factory is extending warranty for this product. All units shipped in the serial number range above will be covered under extended warranty until March 1, 2000. Service Note Z3825A-01 has specific information on component warranty that may provide longer coverage. Please refer to Service Note Z3825A-01 before quoting the repair.

Solution/Action:

1. If during the course of repair it is determined that the GPS Engine is at fault, refer to Service Note Z3825A-01 and follow instructions.
2. If this repair is performed prior to March 1, 2000 charge appropriate warranty charges to Division 0200, using appropriate Failure Codes and Warranty Code "02G".

DATE: July 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

DC

ENTITY:

0200

ADDITIONAL INFORMATION:

