

S E R V I C E N O T E

SUPERSEDES: None

16192A Parallel Electrode SMD Test Fixture**Serial Numbers:** Not available**Repair information on old designed parts****To Be Performed By:** Agilent-Qualified Personnel**Parts Required**

P/N	Qty	Description
16192-00603	1	Plate
16192-60001	1	Contact Assembly

Situation:

the 16192A design has been changed. The following old parts are no longer supplied.

P/N	Qty	Description
16192-00602	1	Plate
16192-60001	1	Contact Assembly
16193-24001	1	Flange

Solution/Action:

When one of the old parts is replaced with the new one, the remaining two old parts should be replaced at the same time. The old Contact Assembly and the new Contact Assembly have the same part number, but they are not the same part. The new Contact Assembly includes a flange portion.

DATE: August 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

KW

ENTITY:

3355

ADDITIONAL INFORMATION: