

hp MODEL 175A OSCILLOSCOPE  
All Serials

Improved Trigger Circuit Stability

The preferred replacement for V101 is an aged tube which has improved drift characteristics. The aged tube eliminates the need to adjust trigger sensitivity several times, after a period of time, as the replaced tube settles down. Order hp Part No. 5080-0411 for replacement of V101.

Change the Part No. of V101 in your hp Model 175A Operating and Service Manual to insure proper replacement in the future.