

S E R V I C E N O T E

SUPERSEDES: None

18281A/FR/SW/S/B/G... Country specific ISDN Pod

Serial Numbers: 3216A00000 / 3216A99999

Modification to remove PS3

18281-66512 Interface PC Board Assembly

Situation:
With NT simulate capabilities, PS3 was provided at unused pins 1 & 2 at the request from the field. Providing PS3 however can create problems when the pins 1 & 2 are used (for other than PS3) in some networks and contention may cause the network to crash.

Solution:
If the 18281 Pod brings down the network, PS3 can be disabled by removing the two jumper wires inside the 18281 pod.

Procedure:

1. Remove cover
2. Locate wires
3. Remove wires
4. Replace cover

DATE: 16 November 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: Labor 0.7 hrs	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AUTHOR: NB	ENTITY: 3800	AGILENT RESPONSIBLE UNTIL: 16 November 1995	
		ADDITIONAL INFORMATION:	