

S E R V I C E N O T E

SUPERSEDES: None

37717B PDH/SDH/Jitter Test Set

Serial Numbers: GB00000000/GB99999999

Build Status: 1.00 and above

Self Test Fail 1052

To be Performed by: Qualified Service Personnel

Situation

Fail 1052 can occur during self test, if the Remote Control port is set to RS-232 and not GPIB.

Action

Before running self tests ensure that the Remote Control Port is set to GPIB.

DATE:January 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

<p>AUTHOR: DBG</p>	<p>ENTITY: E610</p>	<p>ADDITIONAL INFORMATION:</p>
------------------------	-------------------------	--------------------------------