

S E R V I C E N O T E

SUPERSEDES: NONE

37721A Digital Transmission Analyzer**Serial Numbers:** 3015U00101 / 9999U99999**Replacing the A3 Processor Assembly****Situation:**

A3, Processor Assembly, p/n 37721-60003 has been superseded by p/n 37721-60553. However, p/n 37721-60553 is not fitted with an NVM battery or with PROMS. In the event of the A3 Assembly being replaced, a new battery (p/n 1420-0380) must be ordered and fitted to the replacement board. In addition, the PROMS (U2, U57, and U66) should be removed from the old board and fitted to the replacement board.

On the board exchange program, A3, the Processor Assembly, p/n 37721-69003 has been superseded by p/n 37721-69553. In the event of the A3 Assembly being replaced, through the exchange program, a new battery (p/n 1420-0380) must be ordered and fitted to the replacement board. In addition, the PROMS (U2, U57, and U66) should be removed from the old board and fitted to the replacement board. The old board should then be returned to the exchange program.

DATE: 14 JULY 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: JH	ENTITY: 1400	ADDITIONAL INFORMATION:
---------------	-----------------	-------------------------