

3779C-46

S E R V I C E N O T E

SUPERSEDES: None

HP 3779C Primary Multiplex Analyzer

Serial Numbers: 0000U00000/9999U99999

Front connector Panel Replacement.

Situation:

The Lower Front Connector Panel on the HP 3779C is made up of several sub- assemblies - these are marked MP54, MP55 (A and B) MP56 and MP57 in the diagram on page 6-75 of the 3779C/D Service Manual.

If replacing any of these parts, it is now recommended that the complete panel be replaced. This has HP Part Number 03779-62301.

Action:

Update your Service Manual to reflect this change.

DATE: August 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

ENTITY:

ADDITIONAL INFORMATION:

GCH

1400

© 1994 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.

