

S E R V I C E N O T E

SUPERSEDES: NONE

4062F Semiconductor Parametric Test System

Serial Numbers : JP10B00101 / JP10B00113

Modification to improve heat dissipation**Situation:**

The 8110A PGs in the 4062F can overheat and cease functioning after sufficient stress. When this happens, the error message which the PGs report is "SELFTTEST ERROR."

Solution / Action:

The PGs must be upgrade to improve the ventilation. To do so, use the following procedure.

1. Contact "Svc Support HSTD".
2. Swap the PGs in the 4062F to the loaner units.
3. Send them back to HSTD to implement the upgrade.
4. Return to customer and verify the performance of PGs.

DATE: January 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 2.0 Hours		
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: January 1999		
AUTHOR: SY	ENTITY: 3301	ADDITIONAL INFORMATION: Relative Service Note 4062F-02			