

4140B-16

S E R V I C E N O T E

SUPERSEDES: None

**HP 4140B pA Meter/DC Voltage Source**

**Serial Numbers:** 0000A00000 / 9999Z99999

**Duplicate Service Notes:**

4280A-09  
4084A/B-01  
4086A-01

**Recommended replacement for fan assembly**

**To Be Performed By:** HP-qualified personnel

**Parts Required:**

HP P/N	Qty	Description
04140-65100	1	Fan Assembly

**Situation:**

Currently, service manuals of the above products show part number 3160-0273 as the replaceable part number for the fan. However, when a fan fails, it is necessary to rewire pins and connectors on the new fan to connect the fan cable to the instrument. This is because part number 3160-0273 has no connectors.

DATE 14 October 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
<b>INFORMATION ONLY</b>		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
IT	3301	

© 1991 HEWLETT-PACKARD COMPANY  
PRINTED IN U.S.A.



**Solution/Action:**

We recommend using the fan assembly of HP part number 04140-65100 to repair fans on the above products. This fan assembly contains the necessary pins and connectors, and repair time is reduced.