

# 42841A-05

## S E R V I C E N O T E

Supersedes:  
NONE

### 42841A Bias Current Source

Serial Numbers: ALL

Part number for F2/F3/F4/F5 Fuse on A4 Digital Control board

**Parts Required:**

P/N	Description	Qty.
2110-0742	Fuse 1.5A 125.0V NON-Time-Delay	1
2110-0749	Fuse 7.0A 125.0V NON-Time-Delay	1

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
<b>INFORMATION ONLY</b>	
<input checked="" type="checkbox"/> Calibration Required	PRODUCT LINE: WN
<input type="checkbox"/> Calibration NOT Required	AUTHOR: jm
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2013  
PRINTED IN U.S.A.

April 19, 2013  
Rev. 21




**Situation:**

No replacement part-numbers were setup for F2, F3, F4, F5 fuse on A4 board

**Solution/Action:**

When the F2, F3, F4 or F5 fuse blows, replace it with the following parts.

Parts location	Replacement part-number
F2, F3	2110-0749
F4, F5	2110-0742



**Revision History:**

Revision Number	Date	Author	Reason For Change
1.0	18-Apr-2013	jm	As published