

S E R V I C E N O T E

SUPERSEDES: NONE

**4339B High Resistance Meter**

Serial Numbers: JP1KD00101 / JP1KD01157

**Modification to fix incorrect Handler Interface signal**

To Be Performed By: Agilent-Qualified Personnel

**Parts Required:**

P/N	Description	Quantity
04339-85071	4339B ROM Rev.01.04	1

**Situation:**

Usually, the "NO CONTACT" signal of the Handler Interface is asserted when the contact check is failed. However, the "NO CONTACT" signal may not be asserted when contact check fail (N.C.) and overload (OVL D) are happened at the same time.

**Solution / Action:**

Replace the ROM to revision 01.04.

DATE: January 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 0.5 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: KW	ENTITY: 3355	AGILENT RESPONSIBLE UNTIL:	January 2001
		ADDITIONAL INFORMATION:	