

S E R V I C E N O T E

SUPERSEDES: None

4396B Network/Spectrum/Impedance Analyzer

Power supply does not comply with csa950/iec950 standards

Serial Numbers: 4396B: JP1KE00410 / JP1KE00443

WARNING

POWER SUPPLY DOES NOT COMPLY WITH CSA950/IEC950 STANDARDS

Parts Required:

P/N	Description	Quantity
0950-3246	Power Supply	1

Situation:

The power supply board of the 4396B specified above may not comply with CSA950/IEC950 Standards. The clearance/creepage distance between the primary (CR80) and the chassis ground of the power supply may not comply with the clearance/creepage requirements of CSA950/IEC950 Standards.

Solution / Action:

This problem can be fixed by replacing with a new power supply. No adjustments and performance tests are required after this replacement.

DATE: August 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
SAFETY			
ACTION CATEGORY:	<input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 0.5 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	ALWAYS	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: KW	ENTITY: 3355	AGILENT RESPONSIBLE UNTIL: ALWAYS	
		ADDITIONAL INFORMATION:	