

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

4396B-14

S E R V I C E N O T E

Supersedes:
[NONE]

Agilent 4396B Network/Spectrum/Impedance Analyzer

Serial Numbers: JP1KE01175 and above

New Replaceable Parts for Probe Power Supply

Parts Required: See Solution / Action

To Be Performed By: Agilent-Qualified Personnel

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY
AUTHOR: TO PRODUCT LINE: WN
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002
PRINTED IN U.S.A.



October 8, 2002

Situation:

New filter board (P/N E4970-66530) and wire assembly (P/N E4970-61685) were added to the probe power line of the 4396B in order to improve the isolation between the RF circuits and probe power cable. The allocation of replaceable parts for the probe power line was changed.

Solution/Action:

When replacing the new parts of the probe power line, order appropriate parts referring to the following parts list.

Replaceable Parts List:

	P/N	Description	Qty
1	E4970-66530	Filter Board	1
2	04396-61685	Wire Assembly	1
3	04396-66520	A20 Motherboard	1
4	0515-0924	Screw M3	2
5	2190-0584	Washer	2




Figure 1 Filter board replacement