

S E R V I C E N O T E

SUPERSEDES: 4952A-12A

**4952A Protocol Analyzer**

**Serial Numbers:** 0000A00000 / 2945A00000

System Processor/Memory Board/A2 Assembly

**Firmware Rev 1.0 to A.02.02 Upgrade**

**To Be Performed By:** Agilent-Qualified Personnel

**Parts Required:**

P/N	Description
04952-67107	Firmware Rev A.02.02 Upgrade Kit

**Situation:**

The Firmware in the 4952A has been revised to add new testing capabilities and enhancements. The enhancements are:

1. AutoConfigure has been enhanced to work better with BSC and will configure to 50, 75, 14.4K, and 38.4K bps async. Easier to distinguish between X.25, SDLC, and HDLC protocols.
2. The Remote Menu will support the uploading and downloading of the entire 3/4 Mbyte extended capture buffer memory.

*Continued*

DATE: 22 October 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
<b>MODIFICATION AVAILABLE</b>		
ACTION CATEGORY:	<b>AGREEABLE TIME</b>	<input checked="" type="checkbox"/> PERFORMANCE ENHANCEMENT <input type="checkbox"/> SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	AVAILABLE UNTIL: Product Support Life
AUTHOR: RCB	ENTITY: 3800	ADDITIONAL INFORMATION: Reference PCO 09-28696

3. The Print Menu permits the entire 3/4 Mbyte extended capture buffer or portions of it.
4. Two new async speeds have been added that were previously on the Utility Disc, 14.4 and 38.4 Kbps.

**Solution/Action:**

If a customer with a 4952A desires one or more of the new testing capabilities or enhancements, install the Rev A.02.02 Upgrade Kit.

The installation of this kit will be done at the customer's expense.