

DAYTON

MSR 2604

HALLIWELL, BERNARD J

5001A-2

S E R V I C E N O T E

Supersedes:
None

HP MODEL 5001A MICROPROCESSOR EXERCISER

Serial Numbers Below 2040A00321

POWER FUSE (F1) REPLACEMENT

The 5001A with Power Fuse F1 rated at .75A (2110-0577) should be replaced with 1.0 Amp Fuse 2110-0099. The 1.0 Amp Fuse will allow correct derating margin for estimated current draw of the 5001A and external ROM. Please replace the .75A fuse with Serial Number below 2040A00321.

D/OF/WA

9/81-02/SO



For more information contact a local Hewlett-Packard Office. (Hewlett-Packard has 200 Sales and Service Offices in 75 countries). Or write: Hewlett-Packard, 1501 Page Mill Road, Palo Alto, California 94304, U.S.A.

Printed in U.S.A.