

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

54846B-02

S E R V I C E N O T E

Supersedes:
NONE

54846B

Serial Numbers: [0000A00000 / 9999Z99999]

Update on errors in service manual 54846-97002. They will be corrected in next revision.

Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: [initials] PRODUCT LINE: 1A

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002
PRINTED IN U.S.A.

August 6, 2002



Agilent Technologies

Situation:

Page 3-27

The lower limit shown for Time Measurement Accuracy is 24.946ns it should read 24.956ns.

Page 1-3

The Agilent Mouse P/N should be 1150-7913 not C3751-60201.

Page 1-7

Under specifications & characteristics on Page 1-7, "54835A/45A/46A" is printed. It should be "54845B/46B".

Page 1-11

The Display Update Rate should be as follows.

Waveforms/second = >1700

Vpp Measurements/Second = >260

Page 1-12

Under Disk Drive add CDROM description.

Page 1-14

The weight of the instrument should be.

Net = 14kg

Shipping = 17kg.

Page 4-5

Power Supply Voltage Limits table needs to have 3.3V added with limits of 2.8V to 3.5V.

Page 5-13

Under Power Supply Distribution: 3.3V should NOT be generated on Motherboard.

Page 8-3

Filtered voltages needs to have 3.3V added.

Solution/Action:

They will be corrected in next revision of service manual.