S E R V I C E N O T E

SUPERSEDES: None

5DX X-Ray System

Serial Numbers:

Series I Systems Series I to II upgraded Systems Series II Systems Series 2L Systems

Modified spanner wrench for ball screws

Situation:

The spanner wrench tool (E7200-00070) that holds the x-axis and y-axis ball screws stationary while removing the damaged support bearings can itself cause damage to the ball screw shaft. This tool has been modified so that it will not damage the costly ball screw shaft. The part number for the modified tool is still E7200-00070.

Solution / Action:

All CEs should order the modified spanner wrench tool for their 5DX tool kits.

DATE: December 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: ENTITY: ADDITIONAL INFORMATION:

TS 0980

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

