

66312A-07

S E R V I C E N O T E

66312A Dynamic Measurement DC Source

Serial Numbers: GB37440100 - GB37440224

POSSIBLE “SHOCK” HAZARD

WARNING

Front Panel Binding Post “Float Voltage” labeling is incorrect. It should read “+/-50 VDC Max” and Not “+/- 240 VDC Max”. The rear terminals are marked correctly.

To Be Performed By: Agilent-Qualified Personnel or Customer can apply new label provided.

Parts Required:

P/N	Description	Qty.
06611-40007;	Binding Post Spacer;	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
SAFETY			
ACTION CATEGORY:	X ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR: 0.1 Hours
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP X SEE TEXT
AVAILABILITY:	ALWAYS	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP X SEE TEXT
AUTHOR: BM	PRODUCT LINE: 33	AGILENT RESPONSIBLE UNTIL: ALWAYS	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2002
PRINTED IN U.S.A.



February 19, 2002

Situation:

There's a remote possibility of a Shock if the customers exceeds 50 VDC Floating Voltage.

Solution/Action:

A customer letter will be sent notifying them of the problem and a new label will be provided.