INFORMATION ONLY - DOES NOT COMMUNICATE A MODIFICATION OR SAFETY COMMUNICATE

6683A-05

<u>SERVICE NOTE</u>

Supersedes: None

6683A System Power Supply

Serial Numbers: 0000A00000 - MY41000115

"Replacement of the Bias or AC Input Boards"

Situation:

It has been decided to remove the "Dew Detector" feature, beginning with units with serial numbers greater than the given range. The bias and AC Input board part numbers have changed.

Solution:

The Bias board p/n that is compatible with older models with the Dew Detector is: 5065-6936. (Bias boards compatible with newer models without the dew detector feature use p/n: 5064-3450)

The AC Input board p/n that is compatible with older models with the Dew Detector is: 5065-6938. (AC Input boards compatible with newer models without the dew detector feature use p/n: 5064-0014)

Parts Required:

Bias Board: p/n 5065-6936 AC Input Board: p/n 5065-6938

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: RJM PRODUCT LINE: 33

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002 PRINTED IN U.S.A.



June 12, 2002