A MODIFICATION ONLY - DOES NOT COMMUNICATE

6690A-01

S E R V I C E N O T E

Supersedes: None

6690A System Power Supply

Serial Numbers: 0000A00000 - MY41000131

"Replacement of the Bias Board"

Situation:

It has been decided to remove the "Dew Detector" feature, beginning with units with serial numbers greater than the given range. The bias board part number has changed.

Solution:

The Bias board p/n that is compatible with older models with the Dew Detector is: 5065-6937. (Bias boards compatible with newer models without the dew detector feature use p/n: 5065-0646)

Parts Required:

Bias Board: p/n 5065-6937

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: RJM PRODUCT LINE: 33

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002 PRINTED IN U.S.A.



June 12, 2002