

**6691A-01**

**S E R V I C E N O T E**

---

Supersedes:  
None

## 6691A System Power Supply

**Serial Numbers: 0000A00000 – MY41000119**

### “Replacement of the Bias Board ”

**Situation:**

It has been decided to remove the “Dew Detector” feature, beginning with units with serial numbers greater than the given range. The bias board part number has changed.

**Solution:**

The Bias board p/n that is compatible with older models with the Dew Detector is: 5065-6937.  
(Bias boards compatible with newer models without the dew detector feature use p/n: 5065-0646)

**Parts Required:**

Bias Board: p/n 5065-6937

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: <b>INFORMATION ONLY</b>
AUTHOR: RJM    PRODUCT LINE: 33
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002  
PRINTED IN U.S.A.



June 12, 2002