

S E R V I C E N O T E

SUPERSEDES: 70700A-01B

70700A Digitizer

Serial Numbers: 0000A00000 / 3316A00884

Information on new firmware

Situation:

The Modular System Interface Bus (MSIB) integrated circuit is being manufactured by an outside vendor. The original MSIB IC (part number 1820-3010) is being replaced by the 1820-8731. For the 1820-8731 to work in the 70700A Digitizer the firmware needs to be changed and the RAM Down Loadable Program installed.

Solution/Action:

If the MSIB IC (part number 1820-3010) needs to be changed, order the 1820-8731 along with one of the appropriate kits. If the EPROMs, A5U43 and A5U44, need to be changed, the new firmware will function with the 1820-3010.

Part Number	Description
70700-60037	70700A Digitizer STD RAM/ROM Kit
70700-60036	70700A Digitizer H25 RAM/ROM Kit
70700-60035	70700A Digitizer RAM DLP Kit
70700-10022	70700A Digitizer RAM DLP

DATE: 04 January 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
RDS	5340	