

MODIFICATION RECOMMENDED

81150A-08A

S E R V I C E N O T E

Supersedes:
NONE

81150A -Pulse Function Arbitrary Noise Generator

Serial Numbers:

MY47C01211, MY47C01216-MY47C01217, MY47C01219, MY47C01222, MY47C01225, MY47C01235-MY47C01236, MY47C01239- MY47C01241, MY47C01246, MY47C01259, MY47C01263-MY47C01270, MY47C01275, MY47C01277, MY47C01279-MY47C01280, MY47C01282, MY47C01293, MY47C01295-MY47C01296, MY47C01298-MY47C01299, MY47C01305, MY47C01306, MY47C01309, MY47CEX040

Some shipped units have wrong entries in the internal Calibration Table (Calibration data) for three parameters, and could therefore fail Calibration (Performance Verification) in the service center.

Please send back to the factory the affected units for recalibration!

Do not repair these units!

Parts Required:

| P/N | Description | Qty. |
|------|-------------|------|
| NONE | | |

ADMINISTRATIVE INFORMATION

| | | | |
|---------------------------------|--|---|--|
| SERVICE NOTE CLASSIFICATION: | | | |
| MODIFICATION RECOMMENDED | | | |
| ACTION CATEGORY: | XX ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME | STANDARDS | LABOR: 0.0 Hours |
| LOCATION CATEGORY: | <input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE XX SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER | SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP XX SEE TEXT | USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP XX SEE TEXT |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | NO CHARGE AVAILABLE UNTIL: 28-Feb-2012 | |
| AUTHOR: | HK | PRODUCT LINE: 24 | |
| ADDITIONAL INFORMATION: | | | |

© AGILENT TECHNOLOGIES, INC. 2010
PRINTED IN U.S.A.

December 10, 2010

Rev. 17



Situation:

Some shipped units have the problem, that three calibration tables entries were overwritten with default values.

Although we don't expect any of this units to be out of specifications, there is a high risk, that one or more of these three parameters could fail Calibration (Performance Verification).

The following calibration table entries are affected:

- External In Threshold Accuracy (50 Ohm)
- External In Threshold Accuracy (10k Ohm)
- Internal Impedance per Channel

Solution/Action:

To prevent a costly (warranty) repair of the unit, please send back to the factory the affected units for recalibration.

Agilent Technologies Microwave Products (M) Sdn. Bhd.
Attn: Oh Chun Yong
Bayan Lepas FIZ Phase III,
11900 Penang, Malaysia
Direct Line: +6-04-680-4361